

Port of Varanus Island – New Isolated Danger Marker at Jackson Rock

Number: V01/2024

Date: 2/01/2024

Date of Effect:	2/01/2024
Details:	New Isolated Danger Marker at Jackson Rock
Former Notice:	Supersedes V04-2023(T)
Charts & Publications:	Aus 65, Aus 742
Further Notice:	Nil
Attachments:	Nil

Mariners are advised that the Jackson Rock buoy is now operational after being replaced with an isolated danger buoy.

The Jackson Rock buoy is in approx. position 20° 39.873' S, 115° 35.856' E (location depicted in image below).

AtoN type: Isolated danger marker.

Buoy description: Red and black spar buoy.


Day mark: Two (2) black sphere in a vertical line.

Light characteristics: FL (2) W 10s.



Isolated danger buoy

A virtual AToN also exists in approx. position 20° 39.91' S, 115° 35.84' E. MMSI: 995036238



All current local Marine Notices are available on our website: <http://www.pilbaraports.com.au/#marine-notices>

Ashburton VTS | Phone: (08) 9159 6556 | dampier.vts@pilbaraports.com.au

Mariners and other port users are requested to notify the Harbour Master on the discovery of new dangers or suspected dangers to navigation within the Port.

If it is noted by the mariner that incorrect AIS AtoN is being displayed onboard the ship's ECDIS / navigational display(s) or the Pilot's Portable Units (PPU) , this should be reported to AMSA using [Report a Marine Safety Concern form](#) with copy to dampier.vts@pilbaraports.com.au.

Anurodh

Capt. Anurodh Prasad
Harbour Master, Varanus Island



All current local Marine Notices are available on our website: <http://www.pilbaraports.com.au/#marine-notices>

Ashburton VTS | Phone: (08) 9159 6556 | dampier.vts@pilbaraports.com.au

Mariners and other port users are requested to notify the Harbour Master on the discovery of new dangers or suspected dangers to navigation within the Port.