
B15/16 INCORRECT FLASH SEQUENCE - Navigational Aids

Number: PH 04/24

Date Issued: 6/03/2024

Date of Effect:	5 March 2024
Details:	B15/16 INCORECT FLASH SEQUENCE
Former Notice:	N/A
Charts & Publications:	AUS 53
Further Notice:	N/A

Mariners and port users are advised that B15/16 flashing sequence doesn't match the navigational charts, it is now 2 seconds and needs to be 4 seconds. The beacons are illuminating just not chart sequenced.

Pilbara Ports Team are working to rectify the issue as soon as possible.

Any questions or feedback regarding this Local Marine Notice should be addressed to the Port Hedland Marine Operations Team.



**Behrouz Daei Zadeh
Harbour Master East (Port Hedland)**