

Port of Dampier – Dampier Sea Buoy – Aid to Navigation Defect


Number: D14/2025(T)

Date: 16/07/2025

Date of effect:	16/07/2025
Details:	Port of Dampier - Sea Buoy – Change of light characteristics
Former notice:	N/A
Charts and publications:	AUS 57, 59 ENC Cell AU421116
Further notice:	Will be cancelled on rectification
Attachments:	Charlet of the location of the buoy

Mariners are advised that light of ‘Dampier Sea Buoy’ is operating at a reduced intensity - ‘diminished’.

Name	Latitude	Longitude	Nature of Defect
Dampier Sea Buoy	20° 25.45' S	116° 42.92' E	Diminished (Dim)



Capt. Mike Minogue
Harbour Master

Dampier Vessel Traffic Service | Phone: (08) 9159 6556 | dampier.vts@pilbaraports.com.au

Mariners and other port users are requested to notify the Harbour Master on the discovery of new dangers or suspected dangers to navigation within the port. [All current local Marine Notices are available on our website.](#)