## LANDSIDE OPERATIONS (DAMPIER) - NOTICE



## LD25/053 - Diesel unavailable via pipeline at DCW berths

**ATTENTION:** All DCW and Port of Dampier site users

**ISSUE DATE**: 29-09-2025

ISSUED BY: Landside Operations Supervisor (Dampier)

Pilbara Ports is advising that there will be no diesel supply via pipeline available at the Dampier Cargo Wharf (DCW) effective immediately until the 19<sup>th</sup> of October 2025. Deisel bunkering may still be available via road truck or at the Toll Dampier Supply Base (TDSB). We apologise for any inconveniences this may cause.

Please take this notice into consideration for forward planning in the coming weeks.

Any queries should be directed to Landside Operations on 08 9159 6533 or by writing to landside.dampier@pilbaraports.com.au